


Stejnoseměrné motory s permanentními magnety P2SZ...

DC motors PM

Gleichstrommotoren mit PM

Двигатели постоянного тока с ПМ



Typ	Výkon	Napětí	Proud	Ootáčky	Krytí	Provoz	Smysl.toč.	A	B	Hmotnost
	Power	Voltage	Current	Speed	Protection	Duty cycle	Rotation			Weight
	Leistung	Spannung	Strom	Drehzahl	Schutzart	Betrieb	Drehrichtung			Masse
	Мощность	Напряжение	Ток	Обороты	Защита	Режим	Вращение			Масса
	(W)	(V)	(A)	(1/min)						(kg)
P2SZ447	252	24	10,5	3000	IP 54	S1	both	23		3,3
P2SZ467	250	24	14	3000	IP 20	S1	both	23		3,5
P2SZ595	252	24	10,5	3000	IP 44	S1	both	23	24	